

**Illinois Commerce Commission****Pipeline Safety****Pipeline Safety Report****Inspection #: 2015-P-00057**

<b>Operator: AMEREN ILLINOIS COMPANY</b>	<b>Operator ID#: 32513</b>
<b>Exit Meeting Contact: Steve Barkley</b>	<b>Total Man Days: 2</b>
<b>Pipeline Safety Representative(s): Aaron McElravy</b>	
<b>Company Representative to Receive Report: Michael Fuller</b>	<b><u>Emailed Date:</u></b>
<b>Company Representative's Email Address: mfuller2@ameren.com</b>	03/26/2015

**Inspection Summary**

<b>Inspection Type</b>	<b>Location</b>	<b>ICC Analyst</b>	<b>Inspection Unit(s)</b>	<b>Man Day(s)</b>	<b>Inspection Date(s)</b>	<b>Contact(s)</b>
Standard Inspection - Field Audit	Hoopeston, Henning, Armstrong, East Lynn, Alvin, Danville	Aaron McElravy	Hoopeston	2	3/17/2015, 3/18/2015	Robert Roth, Steve Barkley

**Statement of Activities**

On March 17-18, 2015, Staff conducted a Field Audit of the Ameren Hoopeston inspection unit to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590. The audit included inspection of Ameren facilities including customer meters, cathodic protection, damage prevention, pressure limiting and regulating devices, valves and odorization equipment. Staff closed an outstanding issue in reference to 192.479(a) discovered on a previous inspection conducted on December 6, 2011. During the audit no deficiencies were identified. Additional information regarding the specific code sections are identified on the attached inspection form.

**Exit Statement****INSPECTION FINDINGS****Standard Inspection - Field Audit****Issues(s) Found:**

[NO ISSUES FOUND]

**Notice Of Amendment(s) Found:**

[NO NOAS FOUND]

**Notice Of Violation(s) Found:**

[NO NOPVS FOUND]

**PAST INSPECTION FINDINGS****Issue(s) Corrected:****2012-S001-00009** (Code Part [192.479a]) - Staff field verified remedial measures were taken to address deficiencies identified on

# Illinois Commerce Commission

## Pipeline Safety

### Pipeline Safety Report

***Inspection #: 2015-P-00057***

a previous field audit conducted on December 6, 2011. Staff inspected customer meters and regulators at 904 and 909 Sprague Road in Hoopeston for adequate coatings to prevent atmospheric corrosion. This issue will be considered closed based upon this field audit and the corrective action taken.

**Notice Of Amendment(s) Corrected:**

[NO NOAS CORRECTED]

**Notice of Violations(s) Corrected:**

[NO NOPVS CORRECTED]